



The Ultimate Driving  
Machine



**INFORMATION.**  
**SOFTWARE UPDATE.**

# Contents

- Content ..... 2
- Requirements ..... 2
- Installation ..... 2
- Notes ..... 2
- Software Update (TB & MB 001.030.001) ..... 3
- Software Update (TB & MB 001.040.001) ..... 3
- Software Update (TB & MB 001.044.001) ..... 4
- Software Update (TB & MB 001.047.003) ..... 4
- Software Update (TB & MB 002.022.001) ..... 5
- Software Update (TB & MB 002.034.002) ..... 5
- Software Update (TB & MB 003.010.003) ..... 6
- Software Update (TB & MB 005.002.001) ..... 6

# Information about the software update

## Content

These instructions provide information about the software update.

The content of the software update depends on the software version of your vehicle.

Please refer to the following information for details about the software update and supported devices.

Depending on your vehicle, one of the following versions will be installed:

- ▷ TB 001.031.023 & MB 001.031.022
- ▷ TB 001.041.023 & MB 001.041.022
- ▷ TB 001.045.023 & MB 001.045.022
- ▷ TB 001.061.023 & MB 001.061.023
- ▷ TB 002.023.022 & MB 002.023.021
- ▷ TB 002.035.022 & MB 002.035.021
- ▷ TB 003.011.023 & MB 003.010.003
- ▷ TB 005.003.023 & MB 005.002.001

## Requirements

The software update is only available for specific vehicles that are equipped with the USB audio interface.

To check if your vehicle is supported, refer to [www.bmw.com/update](http://www.bmw.com/update) or the compatibility matrix under [www.bmw.com/bluetooth](http://www.bmw.com/bluetooth).

The Owner's Handbook for Navigation, Entertainment, Communication provides additional information about the software update.

## Installation

The installation of the software update requires the acceptance of the of the right of use conditions.

Refer to [www.bmw.com/update](http://www.bmw.com/update).

To install the software update, save the software update file to a USB device in the main directory and connect the USB device at the USB audio interface on the centre armrest.

In addition, observe the notes in the Owner's Handbook for Navigation, Entertainment, Communication under software update.

Following the installation of the software update, the new software version will be displayed in the vehicle:

1. "My Vehicle"
2. "iDrive settings"
3. "Software update"
4. "Show current version"

## Notes

Switch off the vehicle at the end of the software update.

Transmitted data from external devices will be re-synchronized where required.

Tracks or playlists that were played back prior to the software update must be reselected.

This is also required for the restoration of earlier software versions:

1. "My Vehicle"
2. "iDrive settings"
3. "Software update"
4. "Restore software"

When the software is restored or updated by the service partner, manually generated changes for music files may be deleted.

If the following menu item is not displayed correctly after the software update, briefly deactivate Bluetooth for the installation:

1. "Communication"
2. "Manage mobile devices"
3. "Settings"
4. "Bluetooth"

## Software Update (TB & MB 001.030.001)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves the search function for music tracks with numbers for China (some USB devices).
- ▷ It improves the music search for Taiwan (some USB devices).
- ▷ It improves the display of the track index for Taiwan (some USB devices).
- ▷ It improves playlist sorting for China, Hong-kong and Taiwan (some USB devices).
- ▷ It improves the use of more extensive play-back lists (regardless of the device).
- ▷ It improves the support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).

### Telephone

- ▷ It improves the display of Chinese names for China (some Android devices).
- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.
- ▷ It improves the Bluetooth stability for the use of an Apple Watch.

- ▷ It corrects the deactivation function of the on-line trip log.

### Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 001.031.023 & MB 001.031.022
- ▷ Telephone: TB 001.031.023 & MB 001.031.022

## Software Update (TB & MB 001.040.001)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves the search function for music tracks with numbers for China (some USB devices).
- ▷ It improves the music search for Taiwan (some USB devices).
- ▷ It improves the display of the track index for Taiwan (some USB devices).
- ▷ It improves playlist sorting for China, Hong-kong and Taiwan (some USB devices).
- ▷ It improves the use of more extensive play-back lists (regardless of the device).
- ▷ It improves the support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).

### Telephone

- ▷ It improves the display of Chinese names for China (some Android devices).
- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.

- ▷ It improves the Bluetooth stability for the use of an Apple Watch.
- ▷ It corrects the deactivation function of the on-line trip log.

## Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 001.041.023 & MB 001.041.022
- ▷ Telephone: TB 001.041.023 & MB 001.041.022

## Software Update (TB & MB 001.044.001)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves the search function for music tracks with numbers for China (some USB devices).
- ▷ It improves the music search for Taiwan (some USB devices).
- ▷ It improves the display of the track index for Taiwan (some USB devices).
- ▷ It improves playlist sorting for China, Hong-kong and Taiwan (some USB devices).
- ▷ It improves the use of more extensive playback lists (regardless of the device).
- ▷ It improves the support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).

### Telephone

- ▷ It improves the display of Chinese names for China (some Android devices).

- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.
- ▷ It improves the Bluetooth stability for the use of an Apple Watch.
- ▷ It corrects the deactivation function of the on-line trip log.

## Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 001.045.023 & MB 001.045.022
- ▷ Telephone: TB 001.045.023 & MB 001.045.022

## Software Update (TB & MB 001.047.003)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves playlist sorting for China, Hong-kong and Taiwan (some USB devices).
- ▷ It improves the use of more extensive playback lists (regardless of the device).
- ▷ Improved support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).

### Telephone

- ▷ It improves the display of Chinese names for China (some Android devices).
- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.
- ▷ It improves the Bluetooth stability for the use of an Apple Watch.
- ▷ It corrects the deactivation function of the on-line trip log.

## Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 001.061.023 & MB 001.061.023
- ▷ Telephone: TB 001.061.023 & MB 001.061.023

## Software Update (TB & MB 002.022.001)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves the display of the music search for Hongkong (Apple iPhones).
- ▷ It improves the use of more extensive play-back lists (regardless of the device).
- ▷ Improved support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).
- ▷ Eliminates the error when connecting via Screen Mirroring (some devices in Asia).
- ▷ Eliminates the error when switching between audio apps (some Android devices).

### Telephone

- ▷ It improves the contact search for China (regardless of device).
- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.
- ▷ It improves the Bluetooth stability for the use of an Apple Watch.
- ▷ It corrects the deactivation function of the on-line trip log.

## Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 002.023.022 & MB 002.023.021
- ▷ Telephone: TB 002.023.022 & MB 002.023.021

## Software Update (TB & MB 002.034.002)

The software update makes the following adjustments:

### Multimedia

- ▷ It improves the support of music apps (Apple iPhones).
- ▷ It improves the connection stability for the use of Bluetooth audio streaming (regardless of device).
- ▷ Eliminates the error when switching between audio apps (some Android devices).
- ▷ Eliminates the error when connecting via Screen Mirroring (some devices in Asia).

### Telephone

- ▷ It improves the Bluetooth stability for the use of an Apple iPhone.
- ▷ It improves the Bluetooth stability for the use of an Apple Watch.
- ▷ It corrects the deactivation function of the on-line trip log.

## Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▷ Media: TB 02.035.022 & MB 002.035.021
- ▷ Telephone: TB 02.035.022 & MB 002.035.021

## Software Update (TB & MB 003.010.003)

The software update makes the following adjustments:

### Telephone

- ▶ Improves the audio quality after connecting a second telephone.
- ▶ It corrects the deactivation function of the on-line trip log.

### Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▶ Telephone: TB 003.011.023 & MB 003.010.003

## Software Update (TB & MB 005.002.001)

The software update makes the following adjustments:

### Telephone

- ▶ Improves the audio quality after connecting a second telephone.

### Notes

Following the installation of the software update, the current software version will be displayed in the vehicle:

- ▶ Telephone: TB 005.003.023 & MB 005.002.001

## Frequently Asked Questions

There may be instances where the mobile device does not function as expected, even though all preconditions have been met and all the necessary steps have been carried out in the correct

order. Nevertheless, the software update does not function as expected.

Why does the software fail to detect a USB device at the USB interface?

- ▶ USB device contains an additional /BMWDATA/ directory with files for route profile, Gracenote® update or map updates.
- ▶ Rename or delete the /BMWDATA/ directory on the USB device to make sure the desired files of the software update are recognized in the main directory.